

2019-8-21 WAFB - photos showing ST012 Sulfate mixing tank repairs due to 8-6-2019 puncture



Photo 1: View NW over SE side (non-loading side) showing sulfate mixing tank puncture repair. *(photos by wmler, ADEQ)*



Photo 2: View NW over SE side (non-loading side) showing sulfate mixing tank puncture repair and spill containment. *(photos by wmler, ADEQ)*



Photo 3: View South by SW over SE side (non-loading side) showing sulfate mixing tank puncture repair and spill containment. *(photos by wmler, ADEQ)*